
VIN: 1D7HU18276S580384

DECODED: 2006 Dodge Ram Pickup (ST; Sport; SLT; TRX4 off road;

Model Year: 2006

Make: Dodge

Model: Ram Pickup

Trim Level: ST; Sport; SLT; TRX4 off road; Laramie

P0406 CODE DEFINITION:

- Exhaust Gas Recirculation Sensor A Circuit High

5 POSSIBLE CAUSES:

- EGR sensor connector is damaged (check pins for damage, and for moisture)
- EGR sensor has failed
- EGR sensor return circuit is open
- EGR sensor signal is shorted to voltage
- PCM has failed

TOP REPORTED FIX:

- Replaced Exhaust Gas Recirculation (EGR) Valve

2 FREQUENTLY REPORTED FIXES:

- Programmed Powertrain Control Module (PCM)
- Replaced Powertrain Control Module (PCM)

3 OTHER REPORTED FIXES:

- Cleaned Upper Intake Manifold
- Repaired Exhaust Gas Recirculation (EGR) Valve
- Reset Powertrain Control Module (PCM) w/P0404

Disclaimer:

The Possible Causes outlined above may or may not be the cause of your vehicle trouble code(s) being triggered. The Reported Fixes listed are suggestions only, and a fix is not guaranteed by performing any of the above potential solutions. The trouble code summary data may help you pinpoint the type of repair facility that should be consulted. It is strongly recommended that you consult with a knowledgeable professional repair facility for proper diagnosis and repair of trouble code issues. This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.